


Wilson IC Pad



An aerial photograph of an industrial site. In the upper left, there is a rectangular structure containing several large, light-colored cylindrical tanks. To the right of this structure is a long, narrow, rectangular area with a grid-like pattern, possibly a solar panel array or a similar industrial structure. A red text box is located in the lower left, with a red arrow pointing from it to a small red-bordered square on the ground in the lower right. The ground is mostly brown and sandy, with some tire tracks and scattered debris. The Google logo is visible in the bottom left corner.

Secondary Containment of Vapor
Collection Compressor; Soil Impacts
Remained Within Containment





Description:

#1 - Wilson IC Facility



Description:

#2 - Looking Northeast at Vapor Collection Compressor release; Stained Soil is present within secondary containment

Photo Log



Description:

#3 - Looking Northwest at Release Area within secondary containment

Photo Log



Description:

#4 - Looking West at Release Area

Photo Log



Description:

#5 - Looking Southwest at Release Area; Release Suspected at Yellow Line on the right

Photo Log



Description:

#6 - Looking South at Compressor; Suspected Release is Behind Sump in the Center of this photo