

Inspection Photos

04/19/2024

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335632

Inspection Doc: 696205765

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335632



Photo 1: Photos 1-2 taken from the southeast end of the Location. Photos provide an overview of the Location from southwest, west, north to northeast.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335632



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335632



Photo 3: Photo example showing unmarked anchors on Location.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335632



Photo 4: Photo shows what appears to be a rat/mouse hole. Pursuant to 1003.a, all pits, cellars, rat holes, and other bore holes unnecessary for further lease operations will be backfilled as soon as possible after the drilling rig is released to conform with surrounding terrain; hole has not been properly closed, and/or removed pursuant to Rule 1003.a; Operator appears to have bent portions of the pipe over itself in an attempt to cover the hole; work/cover is insufficient to prevent access by wildlife.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335632



Photo 5: Photos examples showing fence at wells and separator equipment is in disrepair.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335632



Photo 6: Photos 6-7 examples showing various unused fence, and pipe observed on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335632



Photo 7: See comments under photo 6.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335632



Photo 8: Photos examples showing lines at tanks have not been capped/plugged.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335632



April 19, 2024



April 19, 2024

Photo 9: Photos taken from the interim areas of the Location. Reclamation form #1745269 indicates an A horizon of 0-10 inches. Soils observed over the interim areas appear to be predominantly subsoils, with topsoil either thinly spread over the site, mixed with the subsoils, or missing.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources