

Inspection Photos

04/19/2024

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335924

Inspection Doc: 696205767

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335924



Photo 1: Photo taken from the south end of the Location, facing north and northeast.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335924



Photo 2: Photos taken from the interim areas on the west end of the Location. Areas appear to have been recently disturbed during pipeline work. Reclamation efforts evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335924



Photo 3: Photos taken from the interim areas on the north end of the Location. Photos examples showing areas of the slopes where vegetation is sparse. Additional reclamation efforts may be necessary to ensure uniform vegetative establishment.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335924



Photo 4: Photos 4-7 examples showing various trash, debris and/or unused equipment observed stored on the Location; materials include pipe, unused fence panels, containers, hose, trash, rubbish etc....



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335924



Photo 5: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335924



Photo 6: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335924



Photo 7: See comments under photo 4.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335924



Photo 8: Photos examples showing lines at tanks missing required cap/plug.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335924



April 19, 2024

Photo 9: Wildlife netting has large holes, and is no longer in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources