

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403762466

Date Received:

04/20/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

. General

sjninspections@ikavenergy.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714000424

Inspection Date: 02/13/2024

FIR Submit Date: 02/15/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

### LOCATION - Location ID: 333568

Location Name: FAIRFIELD FARMS GAS UNIT-M34N7W Number: 31SENW County: \_\_\_\_\_

Qtrqr: SENW Sec: 31 Twp: 34N Range: 7W Meridian: M

Latitude: 37.150515 Longitude: -107.653320

### FACILITY - API Number: 05-067- -00 Facility ID: 333568

Facility Name: FAIRFIELD FARMS GAS UNIT-M34N7W Number: 31SENW

Qtrqr: SENW Sec: 31 Twp: 34N Range: 7W Meridian: M

Latitude: 37.150515 Longitude: -107.653320

### CORRECTIVE ACTIONS:

1 ☒ CA# 192062

Corrective Action: Comply with rule 606.

Date: 03/16/2024

Response: CA COMPLETED

Date of Completion: 04/15/2024

Operator Comment: Unused equipment removed.

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.
----------------------	--

2  CA# 192063

Corrective Action: Comply with rule 605. Install or repair sign.

Date: 03/16/2024

Response: CA COMPLETED

Date of Completion: 04/15/2024

Operator Comment:	Tank sign repaired.
-------------------	---------------------

ECMC Decision: Approved via an AMI

ECMC Representative:	1. Per photo included in attachment provided by operator the tank sign has been repaired.
----------------------	---

## OPERATOR COMMENT AND SUBMITTAL

Comment: CA completed. See attached completion photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Gabby Riley

Signed:

Title: Permitting Specialist I

Date: 4/20/2024 10:28:36 AM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403762466	FIR RESOLUTION SUBMITTED
403762467	Fairfield Farms 3; CA completion photos

Total Attach: 2 Files