

Inspection Photos
Location Name: Megan State H 16-30D Pad
Location ID: 327755



Photo 1: Location of Wellhead



Photo 2: Wellhead Sign

Inspection Photos
Location Name: Megan State H 16-30D Pad
Location ID: 327755




Photo 3: Wellhead



Photo 4: no grounding rod/berm

Inspection Photos
Location Name: Megan State H 16-30D Pad
Location ID: 327755



Photo 5: No grounding rod/berm




Photo 6: Tank Battery Sign

Inspection Photos
Location Name: Megan State H 16-30D Pad
Location ID: 327755



Photo 7: Tank Battery



Photo 8: Debris

Inspection Photos
Location Name: Megan State H 16-30D Pad
Location ID: 327755



Photo 9: Debris



Photo 10: Debris

Inspection Photos
Location Name: Megan State H 16-30D Pad
Location ID: 327755



Photo 11: Debris



Photo 12: Debris

Inspection Photos
Location Name: Megan State H 16-30D Pad
Location ID: 327755



Photo 13: Unused Equipment



Photo 14: Debris