

Inspection Photos

Location Name: REI 38-9, 35-10, HSR-Beebe Draw 4-15, 3-15

Location ID: 336608



Energy & Carbon Management Commission
40.23366, -104.65825, 1444.1m, 56°
Apr 23, 2024 12:05:19



Energy & Carbon Management Commission
40.23372, -104.65755, 1456.4m, 68°
Apr 23, 2024 12:12:02

Photo 1: Wellhead location

Photo 2: Wellhead sign

Inspection Photos

Location Name: REI 38-9, 35-10, HSR-Beebe Draw 4-15, 3-15

Location ID: 336608



Photo 3: Wellhead sign



Photo 4: Unused equipment

Inspection Photos

Location Name: REI 38-9, 35-10, HSR-Beebe Draw 4-15, 3-15

Location ID: 336608



Photo 5: Wellhead Sign



Photo 6: TA Wellhead

Inspection Photos

Location Name: REI 38-9, 35-10, HSR-Beebe Draw 4-15, 3-15

Location ID: 336608



Energy & Carbon Management Commission
40.23382, -104.65782, 1453.2m, 65°
Apr 23, 2024 12:18:41



Energy & Carbon Management Commission
40.23381, -104.65785, 1450.2m, 5°
Apr 23, 2024 12:18:48

Photo 7: Wellhead Sign

Photo 8: TA Wellhead

Inspection Photos
Location Name: REI 38-9, 35-10, HSR-Beebe Draw 4-15, 3-15
Location ID: 336608



Photo 9: Tank Battery Signs



Photo 10: Tank Battery signs

Inspection Photos

Location Name: REI 38-9, 35-10, HSR-Beebe Draw 4-15, 3-15

Location ID: 336608



Photo 11: Debris



Photo 12: Debris

Inspection Photos

Location Name: REI 38-9, 35-10, HSR-Beebe Draw 4-15, 3-15

Location ID: 336608



Photo 13: Debris



Photo 14: Debris

Inspection Photos

Location Name: REI 38-9, 35-10, HSR-Beebe Draw 4-15, 3-15

Location ID: 336608



Photo 15: Debris



Photo 16: Debris

Inspection Photos

Location Name: REI 38-9, 35-10, HSR-Beebe Draw 4-15, 3-15

Location ID: 336608



Photo 17: Debris




Photo 18: Debris

Inspection Photos

Location Name: REI 38-9, 35-10, HSR-Beebe Draw 4-15, 3-15

Location ID: 336608



Photo 19: Debris



Photo 20: Debris

Inspection Photos

Location Name: REI 38-9, 35-10, HSR-Beebe Draw 4-15, 3-15

Location ID: 336608



Photo 21: Debris



Photo 22: Debris

Inspection Photos

Location Name: REI 38-9, 35-10, HSR-Beebe Draw 4-15, 3-15

Location ID: 336608



Photo 23: Leaking tank



Photo 24: Leaking tank