

State of Colorado  
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

12/01/2023

Document Number:

403612179

## ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

**Operator Information**

ECMC Operator Number: 47120 Contact Person: Erik Mickelson  
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (970) 929-4306  
Address: P O BOX 173779 Fax: ( )  
City: DENVER State: CO Zip: 80217-3779 Email: Erik\_Mickelson@oxy.com

**Identification Information**

API Number: 05 - - ECMC Facility ID: 323420 Initial Form 19 or 27 Document number:   
Facility Name: WARDELL Facility Number: 2G-19HZ Facility Type: LOCATION  
Location QtrQtr: NWNE Section: 19 Township: 3N Range: 65W Meridian: 6  
County: WELD Field Name: WATTENBERG  
Federal, Indian or State Lease Number:

## Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional  
Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

## Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 752922 Facility Name: Hochmiller\_84411 Facility Type: Commercial  
Location: QtrQtr: NWNE Sec: 32 Twp: 3N Range: 65W Meridian: 6  
County Name: WELD Latitude: 40.188001 Longitude: -104.683636

**Sample Information:**

The following Sample Information has been reviewed by the ECMC:

Batch ID: 114904 Document Name: Size of file in bytes: 36352 File Name: 2023\_08\_28\_Hochmiller 84411-A Isotech NG4  
ECMC.xls  
SampleType: Matrix:  
Facility ID: 752922 Sample ID: 654040 Sample Name: Hochmiller 84411--A Sample Date: 08/28/2023  
Collection Point: Dom Matrix: WATER Pre Post: Voluntary Post drill  
Project Number: Remediation Number: Complaint Number: NOAV Number:  
Inspection Number: Spill Number: Laboratory: ISOTECH Lab Sample ID: 887618

Batch ID: 114905		Document Name: Size of file in bytes: 28160		File Name: 2023_08_28_Hochmiller 84411--A Isotech SIW ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 654041	Sample Name: Hochmiller 84411--A		Sample Date: 08/28/2023	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 887615		

  

Batch ID: 114902		Document Name: Size of file in bytes: 78848		File Name: 2023_08_28_Hochmiller 84411--A SGS ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 654037	Sample Name: Hochmiller 84411--A		Sample Date: 08/28/2023	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA58169-1		

  

Batch ID: 114904		Document Name: Size of file in bytes: 36352		File Name: 2023_08_28_Hochmiller 84411-A Isotech NG4 ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 654039	Sample Name: Hochmiller 84411--A		Sample Date: 08/28/2023	
Collection Point: Dom	Matrix: GAS	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 887618		

  

Batch ID: 114903		Document Name: Size of file in bytes: 31232		File Name: 2023_08_28_Hochmiller 84411--A Trip Blank SGS ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 654038	Sample Name: Hochmiller 84411--A		Sample Date: 08/28/2023	
Collection Point: TB	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA58171-1		

**Sample Facility Attachment:**

Facility ID	Attach Num	File Name	Document Name	File Type
752922	403612192	2023_08_28_Hochmiller_84411_A_Spigot_Wellhead_Loc.jpg	Photographs	JPG
752922	403612190	2023_08_28_Hochmiller_84411_A_PrePostPurge.jpg	Photographs	JPG
752922	403612189	2023_08_28_Hochmiller_84411_A_FS_ECMC.pdf	Field Data Report	PDF
752922	403612188	2023_08_28_Hochmiller 84411--A SGS.pdf	Analytical Laboratory Report	PDF
752922	403612184	2023_08_28_Hochmiller 84411--A Isotech SIW.pdf	Analytical Laboratory Report	PDF
752922	403612187	2023_08_28_Hochmiller 84411--A Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
752922	403612186	2023_08_28_Hochmiller 84411-A Isotech NG4.pdf	Analytical Laboratory Report	PDF
752922	403612191	2023_08_28_Hochmiller_84411_A_Spigot.jpg	Photographs	JPG
752922	403612193	2023_08_28_Hochmiller_84411_A_Wellhead.jpg	Photographs	JPG

**Sample ECMC Well Related:**

No Sample ECMC Well Related Information Provided.

**General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	04/24/2024
Total: 1 comment(s)		