

Inspection Photos
Location Name: HSR-Engstrom 15-34
Location ID: 328941



Energy & Carbon Management Commission
40.264, -104.76011, 1452.7m, 24°
04/24/2024 10:03:28

Production facility



Energy & Carbon Management Commission
40.26341, -104.7612, 1449.3m, 31°
04/24/2024 10:00:43

Wellhead

Inspection Photos
Location Name: HSR-Engstrom 15-34
Location ID: 328941



Emergency contact number on 4/4/2024



Emergency contact number on 4/24/2024

Inspection Photos
Location Name: HSR-Engstrom 15-34
Location ID: 328941



Debris on 4/4/2024



Debris on 4/24/2024

Inspection Photos
Location Name: HSR-Engstrom 15-34
Location ID: 328941



Energy & Carbon Management Commission
40.26416, -104.75972, 1452.4m, 22°
04/04/2024 11:22:15

Debris on 4/4/2024



Energy & Carbon Management Commission
40.26415, -104.75973, 1454.5m, 65°
04/24/2024 10:04:18

Debris on 4/24/2024