

Inspection Photos

April 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 320859

Inspection Document #: 714000705

Archuleta County, CO

Township:SENE 17 32N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Seibel B 1
Location ID: 320859

4/23/24
+37.027165,-107.409226
151° SE



Photo 1. View of the disturbance taken from the access point facing center.



API #: 007-06125

Inspection Photos
Location Name: Seibel B 1
Location ID: 320859



Photo 2. Impacted surface material observed at well head.

Inspection Photos
Location Name: Seibel B 1
Location ID: 320859

4/23/24
+37.020679,-107.409086
202° S



Inspection Photos
Location Name: Seibel B 1
Location ID: 320859



4/23/24
+37.020271, -107.408563
357° N

Photo 4. View of rill erosion forming and under cutting fence line on location.

Inspection Photos
Location Name: Seibel B 1
Location ID: 320859



4/23/24
+37.020270,-107.409005
129° SE

Photo 5. View of the eastern interim reclamation area facing southeast.
Vegetation comprised of smooth brome.

Inspection Photos
Location Name: Seibel B 1
Location ID: 320859

4/23/24
+37.020270,-107.409005
196° S



Photo 6. Reference area comprised of a irrigated grass field/pasture.