

# Inspection Photos

April 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 442580

Inspection Document #: 714000706

Archuleta County, CO

Township: SENE 17 32N 5W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Seibel B 2  
Location ID: 442580

4/23/24  
+37.021072,-107.406730  
316° NW



Photo 1. View of the disturbance taken from the access point facing center.

Inspection Photos  
Location Name: Seibel B 2  
Location ID: 442580

4/23/24  
+37.021064,-107.407016  
178° S



**Photo 2.** No sign/placard observed for produced water tank.

Inspection Photos  
Location Name: Seibel B 2  
Location ID: 442580

4/23/24  
+37.021537,-107.407223  
178° S



Inspection Photos  
Location Name: Seibel B 2  
Location ID: 442580



**Photo 4.** View of weedy debris observed at the well head.

Inspection Photos  
Location Name: Seibel B 2  
Location ID: 442580

4/23/24  
+37.021537,-107.407223  
58° NE



**Photo 5.** View of the northern interim reclamation area facing northeast.  
Vegetation comprised of crested and intermediate wheatgrass.

Inspection Photos  
Location Name: Seibel B 2  
Location ID: 442580

4/23/24  
+37.021160,-107.407245  
281° W



**Photo 6.** Reference area comprised of crested and intermediate wheatgrass.