

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: Newnam 32H-C264

Loc ID: 437930

Inspection: 709400982



Exhibit A



Exhibit B



Exhibit C

CA: Trash on well pad, including broken boards on the west side of the pad. Comply with rule 606.

CA Resolution: Operator has reported that the identified trash/debris onsite has been appropriately removed to comply with Rule 606.

CA: Failure to control and manage weeds (Russian thistle & kochia) to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606.c

CA Resolution: Operator has reported that the location has been mowed and maintained to address the identified weeds to comply with Rule 606.