

Inspection Photos
Location Name: Pawnee Creek 9-57-18-1H
Location ID: 423841




Photo 1 – Wellhead



Photo 2 – Well Sign

Inspection Photos
Location Name: Pawnee Creek 9-57-18-1H
Location ID: 423841



Energy and Carbon Management Commission
40.74534, -103.7982, 4572.4ft
04/23/2024 11:18:40

Photo 3 – Tank Battery



Energy and Carbon Management Commission
40.74521, -103.79815, 4576.9ft
04/23/2024 11:19:06

Photo 4 – Compressor

Inspection Photos
Location Name: Pawnee Creek 9-57-18-1H
Location ID: 423841



Photo 5 – Unused Down Hole Tools and Polish Rod



Photo 6 – ECDs

Inspection Photos
Location Name: Pawnee Creek 9-57-18-1H
Location ID: 423841



Photo 7 – Heater Treater



Photo 8 – Gas Meter

Inspection Photos
Location Name: Pawnee Creek 9-57-18-1H
Location ID: 423841



Photo 9 – Gas Engine



Photo 10 – Label Faded

Inspection Photos
Location Name: Pawnee Creek 9-57-18-1H
Location ID: 423841



Photo 11 – Signs at Entrance