

Inspection Photos

API: 071-07981

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/24/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the wellsite. There was a leak at the wellhead that left a white residue.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-07981 | Date: 4/24/2024

Inspection Photos



Photo 2. South side of the location facing north. There is white residue and wet soils that flowed off location at this area. th



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-07981 | Date: 4/24/2024

Inspection Photos



Photo 3. There are signs that produced water flowed off the location to the main road. Red arrow points to wet and white residue.

