

# Inspection Photos

API: 071-07576

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 4/24/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the wellsite.





## Inspection Photos



**Photo 2.** It appears there was a produced water leak at the wellhead that that flowed north toward the fill slope.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 3.** Facing southeast at the location and produced water pit.

