

Inspection Photos

April 23rd, 2024

Operator: MorningStar Operating LLC - 10755

Location ID: 334050

Inspection Document #: 714000721

Archuleta County, CO

Township: NENW 8 32N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Candelaria 32-5 8-2, 4
Location ID: 334050

4/23/24
+37.020554,-107.409000
139° SE



Photo 1. View of the disturbance taken from the access point facing center.

Inspection Photos

Location Name: Candelaria 32-5 8-2, 4

Location ID: 334050



4/23/24

+37.020554,-107.409000

98° E

Photo 2. View of the northern interim reclamation area facing east, vegetation comprised of smooth brome and rabbit brush.

Inspection Photos

Location Name: Candelaria 32-5 8-2, 4

Location ID: 334050



Photo 3. View of wattle BMPs that are no longer functioning and over filled with sediment.

Inspection Photos

Location Name: Candelaria 32-5 8-2, 4

Location ID: 334050



4/23/24

+37.036867, -107.419157

162° S



Photo 4. Inadequate/non functional storm water BMPs observed at location access point.

Inspection Photos

Location Name: Candelaria 32-5 8-2, 4

Location ID: 334050



4/23/24

+37.037100,-107.418848

121° SE

Photo 5. Reference area comprised of indian rice grass and juniper.

