

Inspection Photos

April 23rd, 2024

Operator: MorningStar Operating LLC - 10755

Location ID: 320870

Inspection Document #: 714000722

Archuleta County, CO

Township: NENW 8 32N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Candelaria 32-5 8-1
Location ID: 320870

4/23/24
+37.036820,-107.419237
176° S



Photo 1. View of the disturbance taken from the access point facing center.

Inspection Photos
Location Name: Candelaria 32-5 8-1
Location ID: 320870



Photo 2. Rutting observed on location, additional stabilization is needed to minimize site degradation.

Inspection Photos
Location Name: Candelaria 32-5 8-1
Location ID: 320870



4/23/24
+37.036639,-107.419865
39° NE

Photo 3. Weedy kochia debris observed at the tank berm.

Inspection Photos
Location Name: Candelaria 32-5 8-1
Location ID: 320870



Photo 4. View of unused oil and gas equipment observed on location.



Inspection Photos
Location Name: Candelaria 32-5 8-1
Location ID: 320870



4/23/24
+37.036851,-107.419747
319° NW

Photo 5. View of the northern interim reclamation area facing northwest, vegetation comprised of smooth brome and rabbitbrush.

Inspection Photos
Location Name: Candelaria 32-5 8-1
Location ID: 320870



Photo 5. View of reference area comprised of crested wheatgrass and juniper.