

Inspection Photos
Location Name: Gracie LD22-750 PAD
Location ID: 441911



Photo 1 – Wellheads



Photo 2 – LD22-750 Wellhead

Inspection Photos
Location Name: Gracie LD22-750 PAD
Location ID: 441911




Photo 3 – LD22-720 Wellhead



Photo 4 – Gas Lift Injection Meter House