

Inspection Photos
Location Name: Gracie LD22-750 Production Facility
Location ID: 441911



Energy and Carbon Management Commission
40.73049, -103.84797, 4767.8ft
04/24/2024 12:41:06



Energy and Carbon Management Commission
40.73049, -103.84797, 4768.8ft
04/24/2024 12:41:09

Photo 1 – Gas Meter Houses

Photo 2 – Compressor

Inspection Photos
Location Name: Gracie LD22-750 Production Facility
Location ID: 441911



Photo 3 – Compressor



Photo 4 – Instrumental Air Unit

Inspection Photos
Location Name: Gracie LD22-750 Production Facility
Location ID: 441911



Photo 5 – North Separators



Photo 6 – Heater Treater

Inspection Photos
Location Name: Gracie LD22-750 Production Facility
Location ID: 441911



Photo 7 – Tank Battery

Photo 8 – LACT

Inspection Photos
Location Name: Gracie LD22-750 Production Facility
Location ID: 441911



Photo 9 – Water Tanks

Photo 10 – ECDs

Inspection Photos
Location Name: Gracie LD22-750 Production Facility
Location ID: 441911



Photo 11 – VRU and VRTs

Photo 12 – Separators

Inspection Photos
Location Name: Gracie LD22-750 Production Facility
Location ID: 441911



Photo 13 – Maintenance Tank