

Interim Reclamation and Stormwater Inspection

Date: 4/23/24

Operator: Western Operating Company - 95620

Location ID: 317006

Inspection Document #: 713900563

Washington County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Bobcat D Sand Unit #23

Location ID: 317006



Photo 1. The photo was taken at the entrance to the well location facing South. The photo illustrates the access road entrance with cattle guard and operator sign.

Photo 2. The photo was taken at the well location facing Southwest. The photo illustrates the access road to the active wellhead.

Inspection Photos

Location Name: Bobcat D Sand Unit #23

Location ID: 317006



Photo 3. The photo was taken at the well location facing Southeast. The photo illustrates the unmarked guy line anchor.

Photo 4. The photo was taken at the well location facing West. The photo illustrates partially mowed interim and the wellhead.