

Interim Reclamation and Stormwater Inspection

Date: 4/23/24

Operator: Western Operating Company - 95620

Location ID: 317009

Inspection Document #: 713900565

Washington County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bobcat D Sand Unit #20
Location ID: 317009



Photo 1. The photo was taken at the entrance to the well location facing South. The photo illustrates the access road entrance with cattle guard and operator sign.



Photo 2. The photo was taken at the well location facing North. The photo illustrates erosion along the access road.

Inspection Photos
Location Name: Bobcat D Sand Unit #20
Location ID: 317009



Photo 3. The photo was taken at the well location facing Northeast. The photo illustrates an oily puddle below the actively pumping wellhead.



Photo 4. The photo was taken at the well location facing Northeast. The photo illustrates partially mowed interim and the wellhead.