

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/25/2024

Submitted Date:

04/25/2024

Document Number:

696306271**FIELD INSPECTION FORM**Loc ID 432353 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------|
| , | | rbucogccinspectionreports@c hevron.onmicrosoft.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 432354 | WELL | PR | 02/01/2023 | OW | 123-37070 | FISCUS FEDERAL LD23-78HN | PR |

General Comment:[This is a Well and Tank Battery Inspection](#)

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | CONTAINERS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panels | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | Barbed Wire | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-------------------------------|-----|-------|-----------------|
| Type: Emission Control Device | # 2 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: VRU | # 1 | | |

| | | | |
|-----------------------------------|----------------------------------|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Nitrogen Tank | | |
| Corrective Action: | | Date: | |
| Type: Compressor | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|--------------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | OTHER | PBV CONCRETE | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 60 BBLS | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | Shares berm with the Crude Oil Tanks | | | | |
| Corrective Action: | | | | | Date: |

| | | | | | | |
|--------------------|---|----------|----------------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | 300 BBLS | FIBERGLASS AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |

| | | | | | | |
|---|----------|---------------------|---------------------|-------------|-----------------------|--|
| Other (Type) | | | | | | |
| <u>Berms</u> | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| | | | | | | |
| Comment: Shares berm with the Crude Oil Tanks | | | | | | |
| Corrective Action: | | | | Date: | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CRUDE OIL | 5 | 300 BBLs | STEEL AST | | 40.729820,-103.839830 | |
| Comment: | | | | | | |
| Corrective Action: | | | | Date: | | |
| <u>Paint</u> | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| <u>Berms</u> | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | Date: | | |
| <u>Venting:</u> | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | Date: | | |
| <u>Flaring:</u> | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | Date: | | |

