

# Interim Reclamation and Stormwater Inspection

Date: 4/23/24

Operator: Western Operating Company - 95620

Location ID: 435387

Inspection Document #: 713900568

Washington County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

# Inspection Photos

Location Name: Bobcat Sand Unit Battery

435387

Location ID: 435387



**Photo 1.** The photo was taken at the entrance to the well location facing South. The photo illustrates the operator sign at the entrance to the active locations.



**Photo 2.** The photo was taken at the well location facing North. The photo illustrates the erosion on the production facility pad.



# Inspection Photos

Location Name: Bobcat Sand Unit Battery

435387

Location ID: 435387



**Photo 3.** The photo was taken at the well location facing North. The photo illustrates the tank battery and the mowed interim.



**Photo 4.** The photo was taken at the well location facing North. Refer to the comment for photo 2.



# Inspection Photos

Location Name: Bobcat Sand Unit Battery

435387

Location ID: 435387



**Photo 5.** The photo was taken at the well location facing North. Refer to the comment for photo 2.



**Photo 6.** The photo was taken at the well location facing North. The photo illustrates erosion of the pit wall that should be repaired.




# Inspection Photos

Location Name: Bobcat Sand Unit Battery

435387

Location ID: 435387



**Photo 7.** The photo was taken at the well location facing West. Refer to the comment for photo 6.



**Photo 8.** The photo was taken at the well location facing South. Refer to the comment for photo 6.