




99999999

OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

C

| | | | |
|---|-------------------------|---------------------------------|---|
| <input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION | | 1120 Lincoln Street, Suite 801 | |
| <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION | | Denver, CO 80203 | |
| | | (303)894-2100 | |
| API No. 05- <u>123-08508</u> | | LEASE NAME: <u>Denny #3</u> | |
| LOCATION: <u>SWE-527-7N-67W</u> | | OPERATOR: <u>Schlagel, Rich</u> | |
| DATE: <u>10/15/96</u> | | INSPECTOR: <u>Davelka</u> | |
| Insp. Type: <u>PR</u> | Insp. Status: <u>SI</u> | PA: Y N | Pass/Fail: P <u>F</u> Viol.: Y <u>N</u> NOV: Y <u>N</u> |

INSPECTION ITEM**COMMENTS****INPUT**

| | | |
|--|--|--|
| Well ID Signs (Rule 210, 604.c(4)) | <u>wrong well sign</u> | |
| Pits (Reserve/Production) (Rule 902, 903, 904, 905) | | |
| Fences (Rule 603.b.7, 604.C.(3), 1002.A) | | |
| Tank Battery Equipment (Rule 603.b.3, 604) | | |
| Fire Walls/Berms/Dikes (Rule 603.b.12, 604) | | |
| General Housekeeping (Rule 603) | | |
| Spills (Oil/Water) (Rule 907) | | |
| Bradenhead (Rule 207.b) | | |
| Drilling Well/Workover (Rule 317) | | |
| Surface Rehabilitation (Rule 1002, 1003, 1004, 1103) | | |
| Miscellaneous |  00226833 | |

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.