

Operator: *HIGHPOINT OPERATING CORPORATION*
Location Name: *Anschutz Equus Farms 4-62-33 NWNW*
Loc ID: *437854*
Inspection: *713900536*



Exhibit A



Exhibit B



Exhibit C

CA: *Weed debris in the form of tumbleweeds were observed stuck within the location equipment. Tumbleweeds are a troublesome annual non-native weed that easily breaks off at the stem. Operator failed to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606 to remove weed debris.*

CA Resolution: *Weed debris has been removed to comply with Rule 606.*

CA: *Stained soil observed near unplugged hose, loadout lines, within secondary containment of tank batteries and buried tanks. Remove stained soil per Rule 912.a.*

CA Resolution: *Stained soil has been removed to comply with Rule 912.a.*