

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/28SWNW

Location ID: 324145

Date: 4/18/2024



Wellhead – Photo #00728



Separators – Photo #00726

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/28SWNW

Location ID: 324145

Date: 4/18/2024



Tank Battery – Photo #00725



Damaged Culvert – Photo #00730

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/28SWNW

Location ID: 324145

Date: 4/18/2024



Damaged Culvert – Photo #00731