

## Inspection Photos


Location Name: CAERUS PICEANCE LLC, USA-68S97W/5SWNE

Location ID: 322468

Date: 4/23/2024



North Side of Location – Photo #00750



Wellhead – Photo #00751

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, USA-68S97W/5SWNE

Location ID: 322468

Date: 4/23/2024



Separator – Photo #00753



Dehydrator – Photo #00754



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, USA-68S97W/5SWNE

Location ID: 322468

Date: 4/23/2024



Tank Battery – Photo #00755



Gas Meter – Photo #00756