

Stormwater Inspection

April 16, 2024

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 324591

Inspection Document #: 697505276

Jackson County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DWINELL 1
Location ID: 324591



Photo 1. Photo taken of the Operator sign at the tank battery.



Photo 2. Photo taken of the Operator sign at the wellhead.



Photo 3. Photo taken from the southeastern location, facing North. Photo illustrates the location has not been adequately stabilized to minimize erosion, alteration of natural features, removal of surface materials and degradation due to contamination per Rule 1002.e.(1).

Inspection Photos
Location Name: DWINELL 1
Location ID: 324591



Photo 4. Photo taken from the southeastern location, facing West. See comments under Photo 3.

Inspection Photos
Location Name: DWINELL 1
Location ID: 324591



Photo 5. Photo taken from the southeastern location, facing East. See comments under Photo 3.

Note- photo also illustrates sediment laden stormwater is discharging off location.





Photo 6. Photo taken from the southeastern location, facing South. See comments under Photo 3.

Note- photo also illustrates sediment laden stormwater is discharging off location.



Photo 7. Photo taken from the southeastern location, facing South. Photo illustrates sediment laden stormwater discharging off location in violation of Rule 1002.f.

Inspection Photos
Location Name: DWINELL 1
Location ID: 324591




Photo 8. ECMC GIS aerial imagery illustrates the location falls within Greater Sage Grouse Priority Habitat Management Area, as well as Greater Sage Grouse General Habitat Management Area surrounding the location. Note- there are other big game priority habitats nearby.