

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Shell/797-09A

Location ID: 335018

Date: 4/23/2024



**Location Entrance – Photo #00778**



**Wellheads – Photo #00781**

# Inspection Photos

Location Name: LARAMIE ENERGY LLC, Shell/797-09A

Location ID: 335018

Date: 4/23/2024



Separators – Photo #00779

Tank Battery – Photo #00780

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Shell/797-09A

Location ID: 335018

Date: 4/23/2024



**Debris/Stored Equipment – Photo #00782**



**Lack of Stabilization – Photo #00783**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Shell/797-09A

Location ID: 335018

Date: 4/23/2024



**Lack of Stabilization – Photo #00784**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #00786**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC, Shell/797-09A

Location ID: 335018

Date: 4/23/2024



**Unprotected Soil Stockpile (Access Road) – Photo #00776**



**Unprotected Soil Stockpile (Access Road) – Photo #00777**