

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, NLW CONN CREEK-67S97W/8NWNE

Location ID: 324442

Date: 4/23/2024



Wellhead – Photo #00792

Separator/Dehydrator/Meter – Photo #00790

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, NLW CONN CREEK-67S97W/8NWNE

Location ID: 324442

Date: 4/23/2024



Tank Battery – Photo #00794



Unsecured Hatch/Wildlife Entry Hazard – Photo #00791