

Inspection Photos

Location Name: NONSUCH NATURAL GAS INC, CSOC 697-22-66S97W/22NENE

Location ID: 324169

Date: 4/24/2024



Location Entrance – Photo #00812



Wellhead – Photo #00813

Inspection Photos

Location Name: NONSUCH NATURAL GAS INC, CSOC 697-22-66S97W/22NENE

Location ID: 324169

Date: 4/24/2024



Separator/Methanol Tank – Photo #00814



Tank Battery – Photo #00815

Inspection Photos

Location Name: NONSUCH NATURAL GAS INC, CSOC 697-22-66S97W/22NENE

Location ID: 324169

Date: 4/24/2024



Pit Not Netted – Photo #00817



Stored Supplies/Equipment – Photo #00818