

Inspection Photos  
Location Name: Drilling 27N, 27C-32 HZ  
Location ID: 434988



Photo 1: Tank Battery Signs

Photo 2: Debris

Inspection Photos  
Location Name: Dreiling 27N, 27C-32 HZ  
Location ID: 434988



Photo 3: Debris

Photo 4: Debris

Inspection Photos  
Location Name: Dreiling 27N, 27C-32 HZ  
Location ID: 434988




Photo 5: Debris

Photo 6: Debris

**Inspection Photos**  
**Location Name: Dreiling 27N, 27C-32 HZ**  
**Location ID: 434988**



Energy & Carbon Management Commission  
 40.09076, -104.67859, 1480.2m, 12°  
 Apr 29, 2024 11:33:33



Energy & Carbon Management Commission  
 40.09079, -104.67854, 1482.9m, 294°  
 Apr 29, 2024 11:34:03

**Photo 7: Unused gas meter removed**

**Photo 8: Gas meter not annually calibrated.**

**Inspection Photos**  
**Location Name: Drilling 27N, 27C-32 HZ**  
**Location ID: 434988**



**Photo 9: Debris**