


Inspection Photos

Location Name: CAMPBELL JF PAD 17-41D
Location ID: 430790



Energy & Carbon Management Commission
40.14214, -104.68342, 1483.8m, 352°
Apr 29, 2024 13:38:43



Energy & Carbon Management Commission
40.14218, -104.6841, 1484.8m, 55°
Apr 29, 2024 13:37:30

Photo 1: Tank Battery Sign

Photo 2: Gas meter not calibrated

Inspection Photos
Location Name: CAMPBELL JF PAD 17-41D
Location ID: 430790



Photo 3: Unused equipment

Photo 4: Unused equipment