

Inspection Photos
Location Name: Stults 21-32
API Number: 125-07623



1. Lease sign at access intersection.



2. Lease signs at access intersection.

Inspection Photos
Location Name: Stults 21-32
API Number: 125-07623



3. Lease sign at well location.



4. Well location overview.

Inspection Photos
Location Name: Stults 21-32
API Number: 125-07623



5. View of wellhead after soil turned.



6. Additional view of wellhead.