

Caerus Piceance LLC  
Federal 2S-95-15-22  
Location ID: 316614



As entrance signs are replaced additional information is required



Replaced damaged labels



Caerus Piceance LLC  
Federal 2S-95-15-22  
Location ID: 316614



**Unused equipment**



**Relief riser missing rain protection**

**Caerus Piceance LLC  
Federal 2S-95-15-22  
Location ID: 316614**



**Debris**



**Well pad from production pad**

**Caerus Piceance LLC  
Federal 2S-95-15-22  
Location ID: 316614**



**Well pad from Northeast corner**



**Production pad from Southwest corner**

**Caerus Piceance LLC**  
**Federal 2S-95-15-22**  
**Location ID: 316614**



**Production pad from Southeast corner**



**Production pad from Northeast corner**