

**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Remediation Project No 29080**



**Photo 1 – Site photo**



**Photo 2 - Site photo; downed fencing. Soil stockpiles on either side of excavation with no BMPs.**

**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Remediation Project No 29080**



**Photo 3 – Open excavation with downed fencing. Sign notes large soil stockpile in background is clean soil. Smaller soil stockpile is unmarked.**



**Photo 4 - Open excavation with downed fencing. Sign notes large soil stockpile in background is clean soil. Smaller soil stockpile is unmarked.**

**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Remediation Project No 29080**



**Photo 5 – Open excavation. Impacts remain visible in-situ. Downed fencing.**



**Photo 6 - Open excavation; downed fencing.**



**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Remediation Project No 29080**



**Photo 7 – Open excavation; downed fencing.**



**Photo 8 - Open excavation; downed fencing.**

**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Remediation Project No 29080**



**Photo 9 – Downed fencing**



**Photo 10 - Downed fencing**

**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Remediation Project No 29080**



**Photo 11– Downed fencing**



**Photo 12 - Downed fencing**

**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Remediation Project No 29080**



**Photo 13 – Downed fencing**



**Photo 14 - Soil stockpile. Labeled contaminated. Bermed and lined; liner beginning to tear in some locations.**

**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Remediation Project No 29080**



**Photo 15 – Soil stockpile. Labeled contaminated. Bermed and lined; liner beginning to tear in some locations.**



**Photo 16 - Soil stockpile. Labeled contaminated. Bermed and lined; liner beginning to tear in some locations.**

**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Remediation Project No 29080**



**Photo 17 – Soil stockpile. Labeled contaminated. Bermed and lined; liner beginning to tear in some locations.**



**Photo 18 - Soil stockpile. Labeled contaminated. Bermed and lined; liner beginning to tear in some locations.**



**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Remediation Project No 29080**



**Photo 19 – Small soil stockpile. No BMPs**



**Photo 20 - Small soil stockpile. No BMPs**