

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 01/11/2024 Document Number: 403652055

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 10254 Contact Person: Jacob Harter Company Name: RED MESA HOLDINGS/O&G LLC Phone: (970) 946-3761 Address: 5619 DTC PARKWAY - STE 800 Fax: () City: GREENWOOD VILLAGE State: CO Zip: 80111 Email: jharter@cottonwoodconsulting.com

Identification Information

API Number: 05 - 067-05346 ECMC Facility ID: 214054 Initial Form 19 or 27 Document number: 403253498 Facility Name: DUDLEY Facility Number: 2 (OWP) Facility Type: WELL Location QtrQtr: SWNW Section: 23 Township: 33N Range: 12W Meridian: County: LA PLATA Field Name: RED MESA Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: RED MESA HOLDINGS/O&G LLC Agent Name: Jacob Harter Title: Consultant Phone Number: 970-946-3761 Email: jharter@cottonwoodconsulting.com

Rule 909.J Inspection Information

Date the Pit was Inspected On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 214054 Facility Name: DUDLEY 2 (OWP) Facility Type: Location: QtrQtr: SWNW Sec: 23 Twp: 33N Range: 12W Meridian: N County Name: LA PLATA Latitude: 37.090240 Longitude: -108.127850

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 116108 Document Name: Size of file in bytes: 89600 File Name: Dudley (OWP) #2 Soil Sample EDD (1).xls Sample Type: Matrix: Facility ID: 214054 Sample ID: 655364 Sample Name: Dudley (OWP) #2 Sample Date: 10/19/2023 Collection Point: WellHead Matrix: SOIL Pre Post: Remediation Project Number: Remediation Number: 27455 Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2310204-01

Sample Facility Attachment:

No Facility Attachment

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	The data submitted by the operator can be accessed through COGIS data system.	04/30/2024
Total: 1 comment(s)		