

Inspection Photos

April 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 456613

Inspection Document #: 714000730

Archuleta County, CO

Township: NENE 13 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ross 2
Location ID: 456612

4/23/24
+37.022438,-107.443978
175° S



Photo 1. View of the abandoned well location. No evidence that location was ever constructed.