

Inspection Photos
Location Name: Doris Ackerson Unit 2
Location ID: 318223



Photo 1 gear box leak on pumping unit



Photo 2 gear box leak on pumping unit