

Inspection Photos
Location Name: KC B-65N64W/12SWSE
Location ID: 331865



Photo #1
KC B 12-15 Wellsite
Temporarily Abandoned | TA
wellsite entrance



Photo #2
KC B 12-15 (123-21415) Wellsite
Temporarily Abandoned | TA



Inspection Photos
Location Name: KC B-65N64W/12SWSE
Location ID: 331865



Photo #3

Thomson B 12-25, 12-12, 3-12, KC B 12-15 Battery site

Inactive | Shut-down

Formerly served:

Thomson B 12-13, 4-12; Plugged & Abandoned | PA

Equipment Documented; Loc ID: 302163



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources