

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2024

Submitted Date:

04/30/2024

Document Number:

707602610

FIELD INSPECTION FORM

Loc ID 331865 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267079	WELL	TA	12/20/2021	OW	123-21415	KC B 12-15	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 4 Location IDs (302163, 326975, 330544, 331865).
(Well(s): 4: Temporarily Abandoned | TA).

Centralized Battery Formerly served 2 Location IDs (323044, 330545).
(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707602604 and/or Location ID #302163 for TA Well(s) info.
B.) Field Inspection Report doc. #707602606 and/or Location ID #326975 for TA Well(s) info.
C.) Field Inspection Report doc. #707602608 and/or Location ID #330544 for TA Well(s) info.
D.) Field Inspection Report doc. #707602610 and/or Location ID #331865 for TA Well(s) info.
E.) Field Inspection Report doc. #707602612 and/or Location ID #323044 for PA Well(s) info.
F.) Field Inspection Report doc. #707602614 and/or Location ID #330545 for PA Well(s) info.
G.) Field Inspection Report doc. #707602616 and/or Location ID #302163 for Battery / Facility, Equipment info.

Location

Lease Road:

	Type Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:

					corrective date
Type: Other	# 1				
Comment:	Wellhead: w/ Master, casing valves.				
Corrective Action:					Date:
Type: Plunger Lift	# 0				
Comment:	Temporarily Abandoned TA. Equipment removed.				
Corrective Action:					Date:
Type: Bradenhead	# 1				
Comment:	Appears plumbed to surface.				
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.410165,-104.502374

Comment:	Centralized Battery serves 4 Location IDs (302163, 326975, 330544, 331865). (Well(s): 4: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 267079 Type: WELL API Number: 123-21415 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Locked-out, Tagged-out | LOTO.
Blue TA tag posted.
OOSLAT at separator.
CECMC records last prod: 04/2020.

Form 4 on file. TA date: 11/11/2021. Approved.
DH-CIBP set.
Form 21-MIT on file. MIT date: 11/17/2021. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 04/09/2020. Approved.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 07/31/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 04/29/2024 at approximately 15:04 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: KC B-65N64W/12SWSE Location ID: 331865 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	04/30/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602611	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6531303