

Inspection Photos

Location Name: SLW-65N64W/12SESE

Location #: 323199



Photo #1

SLW 2-12 (123-12701) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 50 yds.



Photo #2

KC B 12-10 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

SLW 2-12 ;

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources