

Inspection Photos
Location Name: TREBOR-65N64W/12SWNE
Location #: 323714



Photo #1
Trebor B12-7 Wellsite
Temporarily Abandoned | TA
wellsite entrance



Photo #2
Trebor B12-7 (123-13406) Wellsite
Temporarily Abandoned | TA
CA: Overgrown Vegetation



Inspection Photos

Location Name: TREBOR-65N64W/12SWNE

Location #: 323714



Photo #3

Trebor B12-7 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Trebor B12-2, Trebor B12-6 ;

Plugged & Abandoned | PA



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources