

Inspection Photos

Location Name: TREBOR B-65N64W/12SEnw

Location #: 310485



Photo #1

Trebor B 12-19 (123-26466) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 5 yds.



Photo #2

Trebor B12-5 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Trebor B 12-19 ;

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources