

Inspection Photos

Location Name: LARAMIE ENERGY LLC, CC/0610-24-43 Pad

Location ID: 324314

Date: 4/24/2024



Location Entrance – Photo #00848



Wellhead – Photo #00849

Inspection Photos

Location Name: LARAMIE ENERGY LLC, CC/0610-24-43 Pad

Location ID: 324314

Date: 4/24/2024



Separator – Photo #00851



Tank Battery – Photo #00852

Inspection Photos

Location Name: LARAMIE ENERGY LLC, CC/0610-24-43 Pad

Location ID: 324314

Date: 4/24/2024



Unprotected Soil Stockpile – Photo #00854