

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403776071

Date Received:
05/01/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
ERIN JOSEPH	970-515-1169	ECMCInspections@Oxy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 697602346
Inspection Date: 04/17/2024 FIR Submit Date: 04/25/2024 FIR Status:

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 328358

Location Name: WARDELL-63N65W Number: 19NWNW County:
Qtrqtr: NWN Sec: 19 Twp: 3N Range: 65W Meridian: 6
W
Latitude: 40.216362 Longitude: -104.713826

FACILITY - API Number: 05-123-00 Facility ID: 485891

Facility Name: Wardell H 19-2J Flowline Number:
Qtrqtr: NWN Sec: 19 Twp: 3N Range: 65W Meridian: 6
W
Latitude: 40.216362 Longitude: -104.713826

CORRECTIVE ACTIONS:

1 CA# 194716

Corrective Action: Operator shall properly dispose of oily waste in accordance with Rule 905.e. Additionally, Operator shall manage waste in compliance with Rule 913.b. (5)B and ECMC Guidance 913.b.(5)B i-v.

Date: 05/02/2024

Response: CA COMPLETED Date of Completion: 04/30/2024

Operator Comment: SEE ATTACHED LOCATION PHOTOS. • All the stockpiled soil observed during the inspection was hauled to the Buffalo Ridge Landfill on the day of the inspection. Due to tight spacing on site, excavated soil needed to be stockpiled prior to being loaded on trucks rather than being loaded directly into the trucks by the excavator. No stockpiled soil remained overnight. On the day of the inspection, 4/17/2024, 46 loads of soil were transported to

the Buffalo Ridge Landfill.

ECMC Decision: _____

ECMC
Representative:

2 CA# 194717

Corrective Action: Operator shall submit a Form 27 for Spill ID 485891 that includes a specific workplan and timeline to address the remaining impacts. No Form 27 has been submitted at the time of this inspection.

Date: 04/18/2024

Response: CA COMPLETED

Date of Completion: 04/04/2024

Operator
Comment:

The most recent Form 27 (Doc #403705141) for the facility was submitted on 04/04/2024, and the associated spill/release ID is 485355 and not 485891 as referenced in the inspection.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ERIN JOSEPH

Signed: _____

Title: SR REGULATORY ADVISOR

Date: 5/1/2024 2:30:56 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403776081	LOCATION PHOTOS
-----------	-----------------

Total Attach: 1 Files