

Inspection Photos
Location Name: Badding Tank Battery 20-26SX
Location ID: 421518



Photo 1 Location.



Photo 2 Location.

Inspection Photos
Location Name: Badding Tank Battery 20-26SX
Location ID: 421518



Photo 3 Location.



Photo 4 TB.

Inspection Photos
Location Name: Badding Tank Battery 20-26SX
Location ID: 421518



Photo 5 TB signs.



Photo 6 Horizontal Heated Separators.



Inspection Photos
Location Name: Badding Tank Battery 20-26SX
Location ID: 421518



Photo 7 VRU.



Photo 8 Horizontal Heated Separators & LOTO risers.

Inspection Photos
Location Name: Badding Tank Battery 20-26SX
Location ID: 421518



Photo 9 ancillary equip.



Photo 10 Compressed air dryer.

Inspection Photos
Location Name: Badding Tank Battery 20-26SX
Location ID: 421518



Photo 11 ECD.



Photo 12 Gas Meter Runs, Cards indicate current calibration.

Inspection Photos
Location Name: Badding Tank Battery 20-26SX
Location ID: 421518



Photo 13 LACT.



Photo 14 PW tank & a VRT.

Inspection Photos
Location Name: Badding Tank Battery 20-26SX
Location ID: 421518



Photo 15 Gas meter run, VRT, ECDs.



Photo 16 ECDs.

Inspection Photos
Location Name: Badding Tank Battery 20-26SX
Location ID: 421518



Photo 17 Horizontal Heated Separators.



Photo 18 VRU.

Inspection Photos
Location Name: Badding Tank Battery 20-26SX
Location ID: 421518



Photo 19 Horizontal Heated Separators.



Photo 20 LOTO risers.