

Interim Reclamation and Stormwater Inspection

Date: 4/29/24

Operator: PDC Energy Inc - 69175

Location ID: 470630

Inspection Document #: 713900576

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Ella-64N66W 5SWNW
Location ID: 470630



Photo 1. The photo was taken at the tank battery location facing West. The photo illustrates the operator sign at the tank battery.



Photo 2. The photo was taken at the tank battery location facing East. The photo illustrates the tank battery equipment and edge of the production pad.

Note - The green vegetation along the interior of the fencing appears to be Kochia.

Inspection Photos
Location Name: Ella-64N66W 5SWNW
Location ID: 470630



Photo 3. The photo was taken at the tank battery location facing West. The photo illustrates an example of multiple erosional rills along the production pad.



Photo 4. The photo was taken at the tank battery facility facing North. The photo illustrates unused equipment being stored on the production pad.



Photo 5. The photo was taken at the tank battery facility facing Northeast. The photo illustrates an unused area of the production pad that remains as well as former production area that has been overgrown with Russian thistle and Kochia.



Photo 6. The image is of the tank battery facility using Google Earth imagery. The red box indicates the area formerly used on the tank battery facility that is dominated by Russian thistle and Kochia and should continue to be managed as part of the interim reclamation area. The yellow box indicates the area of the production pad that is storing unused equipment.