

Inspection Photos
Location Name: Haudrich #1
Location ID: 317874



Photo 1 loc pic



Photo 2 Well head and well sign has wrong name

Inspection Photos
Location Name: Haudrich #1
Location ID: 317874



Photo 3 dead men not properly marked



Photo 4 dead men not properly marked

Inspection Photos
Location Name: Haudrich #1
Location ID: 317874



Photo 5 TNK BTRY NFPA placards faded or missing



Photo 6 produced water tank NFPA placard faded

Inspection Photos
Location Name: Haudrich #1
Location ID: 317874



Photo 7 riser does not have proper OOSLAT tag



Photo 8 Hole in secondary containment allowing sediment to leave containment and run off location.

Inspection Photos
Location Name: Haudrich #1
Location ID: 317874



Photo 9 Meter run. Meter run not operational and has not annul calibration card. Debris: dead weeds around meter



Photo 10 HOZ Sep Debris: dead weeds around equipment