

Inspection Photos

04/29/2024

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 323927

Inspection Doc: 696205799

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323927



Photo 1: Photos taken from the west end of the Location, facing east and southeast. Photos provide an overview of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources