

Inspection Photos

04/29/2024

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 383131

Inspection Doc: 696205805

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 383131



April 29, 2024



April 29, 2024

Photo 1: Photos taken from the northern areas of the Location. Vegetation within these areas are predominantly undesirable plant species such as annual mustards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 383131



Photo 2: Photo shows vegetation within northern areas of the Location are predominantly undesirable plant species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 383131



Photo 3: Photo right taken from the southern end of the Location. Photo right taken from the access road. These areas appear to be progressing towards 1004 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 383131



Photo 4: Photo example of vegetation on the adjacent reference area.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources